IBM XIV Storage GUI and XCLI V2.3.1

Release Notes

December 2nd, 2008

1 Installation

From the Unix shell, run:

tar xfvz package-file

This will create a directory with the CLI utility.

2 Known Issues in Version 2.3.1

2.1 XCLI Issues:

2.1.1 **Issue:** Error code MCL_NETWORK_ERROR is seen upon running a CLI command.

Reason: This is a temporary condition that should go away within one minute. Note that the command may have in fact been executed correctly.

Corrective Action: Wait one minute and check if the previous command completed successfully. If not, repeat the command.